PERSONNEL SAFETY PLAN

SITE NAME: Chenical Processors

SITE LOCATION: Pice 9/

Scattle, WA

USEPA RCRA 3012680

NOTE

This plan should be used for inspections at operating facilities only and is in part dependent upon and superseded by the specific facility site safety plan. However, this plan must be completed as appropriate, prior to performing an inspection pursuant to the rules and regulations for the management of hazarous waste under RCRA.

I. Purpose

The purpose of this plan is to assign responsibilities, establish personnel protection standards, mandatory operating procedures, and provide for contingencies that may arise while an inspection is being conducted at the site.

II. Applicability

The provisions of the plan are mandatory for all EPA personnel and personnel under contract to EPA present at the site while inspection activities are being conducted.

Safety Officer

- A. At the site, the Safety Officer shall to the extent practical:
 - Conduct site monitoring of personnel hazards to determine the degree of hazard present.
 - Determine personnel protection levels and necessary clothing and equipment to ensure the safety of personnel.
 - 3. Evaluate weather and chemical hazard information, and recommend to the investigations team leader any necessary modifications to work plans and personnel protection levels to maintain personnel safety.
 - Monitor the safety performance of all personnel to ensure that the required practices are employed.

B. The Safety Officer for this site is:	
---	--

V. INITIAL HAZARD ASSESSMENT CHECKLIST

protective clothing.

In conducting inspections of permitted hazardous waste management facilities or those facilities with interim status, assessing the potential hazard of the particular site before entry may not require extensive field monitoring. However, detailed hazard assessment procedures are outlined below for those sites suspected of presenting a high level of risk so that the inspector may enter the facility with the necessary protective clothing and equipment.

In order to determine whether to enter a potentially hazardous field site and to determine the appropriate level of protective equipment to be worn when entering, the nature and extent of the hazard first must be assessed. The following is a decision logic for this procedure:

asses.	sea. The reviewing real and a sea an			
			ICA /N	BILITY
1.	Prior to on-site arrival, reviewed evidence of potential exposure. The review should include any information available concerning the site and the hazardous waste hand	[led.		_]
2.	Reviewed available toxicological information including texts, computer data via phone link-up (OHM-TADS), manuals (CHRIS), etc.	ſ	1]
3.	After reviewing the available environmental and toxicological information, choose protective clothing according to the types and levels of waste material handle	[d.]
	Level A			
	Level A protection must be worn when the inspector makes a reasonable determination that the highest available level of both respiratory and skin (and eye) contact protection needed. It should be noted that while Level A provides may available protection, it does not protect against all possible hazards. Consideration of the heat stress that can arise wearing Level A protection should also enter into the instance influence work rate, scheduling, and other work practices.	is ximum ible rom ector	·'s]
	Level B			
	The inspector must select Level B protection when the highest level of respiratory protection is needed, but hazardous material exposure to the few unprotected areas the body (i.e., the back of the neck) is unlikely with Level	[of vel B		_]

Level C

The inspector may select Level C when the required level of respiratory protection is known, or reasonably assumed to be, not greater than the level of protection afforded by air purifying respirators, and hazardous materials exposure to the few unprotected areas of the body (i.e., the back of the neck) is unlikely with Level C protection clothing.

Level D

Level D is the basic work uniform. For routine compliance inspection, civilian clothes may be worn. Outer protective gear should be available for use if required. Coveralls may be worn as necessary.

If conditions requiring levels A or B are assessed to exist, the RCRA inspector should seek the support and expertise of a trained emergency response team and defer entry to that response team.

WARNING:

If there is evidence of a significant fire or explosive potential or high levels of nuclear radiation where protective equipment would not be adequate, entry is totally unadvisable.

EMERGENCY TELEPHONE NUMBERS

Immediate	Emergencies	
1.	Police Department	Phone:
2.	Fire Department	Phone: 911
3.	Ambulance Name:	Phone:
Emergency	Support	
1.	U.S. EPA Operations Office Contact Name:	Phone:
2.	Hospital Name: Address:	Phone:
State Off	icials	
1.	State Hazardous Waste Program C Contact Name: Address:	